

SAE/ISO Fire Containment Covers (FCCs) and Fire Resistant Containers (FRCs) Standards Development




Presented to: International Aircraft Systems Fire Protection Working Group

By: Dave Blake, FAA Fire Safety

Date: May 22-23, 2013



Federal Aviation
Administration



Fire Containment Covers

- Standards SAE AS6453 and ISO/CD 14186 are in the final approval phase and should be published shortly.
- The SAE and ISO standards are essentially identical.
- Suggested changes to these standards have been generally accepted and will be incorporated in the next revisions.
- FAA intends to issue a revision to TSO C90 that will reference the new SAE AS6453 standard.



Fire Resistant Containers

- ISO TC20/SC9 committee has approved a new project to develop a standard for FRCs and the effort has commenced.
- Preliminary discussions indicate the new FRC standard will be very similar to the FCC standards.
- SAE will formally begin its version of the standard development at a meeting in Montreal in September 2013.
- ISO will continue its development work at a meeting in Stockholm? in October 2013. (Not certain of meeting details)
- FAA intends to issue a TSO for FRCs that will reference the new SAE standard.



Class-B Fires in AAY Containers

Dhaval Dadia

Dhaval.dadia@faa.gov

609-485-8828

Presented to: International Aircraft Systems Fire
Protection Working Group. Long Beach, CA

By: Dave Blake, FAA Technical Center Fire Safety

Date: Nov 14-15, 2012



Federal Aviation
Administration



AAV Container Tests

- Volume of Container: 12.8 m³ (452 ft³)
- Initial Oxygen quantity: 2.7 m³
- Quantity of fuel burned to consume all available oxygen: 1.3 L
- Heat release of 1.3L of JP-8 = **45.17 MJ**


Test Conditions

- **8"x8"x3" Fuel pan instrumented with igniters and a thermocouple.**
- **Test 1: Empty 12.8 m³ container with pan in the middle of the container holding 1.3 L of JP-8. 30 mL of Heptane used to ignite the fuel.**
- **Test 2: 12.8 m³ container filled with 60 boxes filled with 2.5 lbs of shredded paper each. Pan holding 1.3 L of JP-8 with 30 mL of Heptane to ignite the fuel.**


Fuel Pan Setup



Test within an Empty Container



Test within a Loaded Container




Observations

- **Test 1: Empty Container. ~500 mL consumed.**
 - Total Heat release = $0.5\text{L} \times 0.8 \text{ kg/L} \times 43.1 \text{ MJ/kg} = 17.2 \text{ MJ}$
 - Heat Release Rate = $17.2 \text{ MJ} / 1050 \text{ secs} = 16.4 \text{ kW}$
- **Test 2: Loaded Container. ~400 mL consumed.**
 - Total Heat release = $.4\text{L} \times 0.8 \text{ kg/L} \times 43.1 \text{ MJ/kg} = 13.8 \text{ MJ}$
 - Heat Release Rate = $13.8\text{MJ} / 780 \text{ secs} = 17.7 \text{ kW}$
- **Calculations show burning 500mL of JP-8 in the empty container at ideal stoichiometric conditions would leave ~13% oxygen within the container.**


Oil Burner Heat Release Rate by Heat of Combustion (Appendix F Part III Test)

- **Calculated using the following conditions**
 - Burner runs at 2 gals/hr for 5 minutes (0.63L JP-8)
 - Total Heat Release
$$0.63\text{L} * 0.8 \text{ kg/L} * 43.2 \text{ MJ/kg} = 21.7\text{MJ}$$
 - Average Heat Release Rate
$$21.7\text{MJ}/300 \text{ seconds} = 72.3 \text{ kW}$$

Oil Burner Heat Release by Oxygen Consumption Calorimetry Hood



Oil Burner Heat Release by Oxygen Consumption Calorimetry Hood



Heat Release by Oxygen Consumption

- Average heat release rate = **77.7kW**
- Total Heat Release over a 5 minute test duration
- $77.7\text{kW} \times 300 \text{ secs} = \mathbf{23.3\text{MJ}}$

Summary

	Time of Burning (seconds)	Total Heat Release (MJ)	Heat Release Rate (KW)	Fuel Consumption Rate
Oil Burner Heat of Combustion	300	21.7	72.3	2.1 mL/sec
Oil Burner Oxygen Consumption Calorimetry	300	23.3	77.7	2.1 ml/sec
Pan in an empty AAY	1050	17.2	16.4	0.47ml/sec
Pan in loaded AAY	780	13.8	17.7	0.51 ml/sec

Conclusion: The Appendix F Part III oil burner test represents a more severe fire exposure condition than an internal flammable fluid (Class B Fire) within a FCC or FRC due to the limits of available oxygen to sustain an internal fire.



Unresolved Issues:

- Possible delayed smoke detection from a fire originating in either a FCC covered pallet or inside a FRC.
- Certification requirements if an FRC also contained a fire suppression system.
- Intumescent coating effectiveness assurance after time in service.

